

A detailed technical drawing of a mechanical assembly, likely a printing press component. The drawing includes several numbered callouts: 1 points to a vertical stack of components on the left; 2 points to a vertical stack of components on the right; 3 points to a horizontal component below 1; 4 points to a horizontal component below 3; 5 points to a horizontal component below 4; 6 points to a horizontal component below 5; 7 points to a horizontal component below 6; 8 points to a vertical component on the right; 9 points to a horizontal component on the right. The drawing also shows a cross-section view of a component at the bottom, labeled with 'A' and 'B'.






Fig. 2




Fig. 3